



**Wildlife Survey & Photo Service**

2443 Fair Oaks Blvd. # 209 • Sacramento, CA 95825 • (916) 747-8537

## REPORT 4080

Cold & Thompson Creeks

March 23, 2012

To: Rich Marovich

Per our recent discussion, the storms during the week of March 12th, 2012, created a situation where I thought Thompson Creek would be ripping. WRONG. Thompson creek was dry, the images below show the significant flow coming from Cold Creek Canyon on March 14, 2014.



Cold Creek looking down-stream toward Putah Creek on 3/14/2012



Cold Creek Confluence with Putah Creek. Note that Putah Creek upstream from Cold Creek was flowing clear. 3/14/2012



## Wildlife Survey & Photo Service

2443 Fair Oaks Blvd. # 209 • Sacramento, CA 95825 • (916) 747-8537



Thompson Creek on  
3/14/2010.

Submitted via e-mail 3/24/12

Ken W. Davis  
Aquatic Biologist  
Wildlife Survey & Photo Service  
2443 Fair Oaks Blvd. # 209  
Sacramento, CA 95825  
(916) 747-8537