



Wildlife Survey & Photo Service

2443 Fair Oaks Blvd. # 209 • Sacramento, CA 95825 • (916) 747-8537

REPORT

Putah / Thompson - 4074

March 1, 2012

To: Rich Marovich
Putah Creek Streamkeeper

Per our discussion about having Rick Poore look at the confluence of Thompson Creek and Putah Creek, I have provided the images below to assist in that effort if you decide it is necessary. I accompanied Rick into Thompson Canyon, but do not believe he looked at the confluence. All images are available upon request.

Ken W. Davis

Aquatic biologist



Merged image of the islands at the Thompson Creek Confluence with Putah Creek. Image made from five separate images of the site to provide. Image **Putah-4074-26-PAN-1** taken March 2, 2012.



Sediment "Islands" as photographed from access road to Monticello Dam



Wildlife Survey & Photo Service

2443 Fair Oaks Blvd. # 209 • Sacramento, CA 95825 • (916) 747-8537



Thompson Creek image upstream from access road (bridge) to Monticello Dam. Image: **Thompson3444_Panorama1 - 4-16-08**



Wildlife Survey & Photo Service

2443 Fair Oaks Blvd. # 209 • Sacramento, CA 95825 • (916) 747-8537



Sediment delta from Thompson Creek. Thompson Creek enters from left.
Image: 3429-226-ST-ST2 - 2/11/10



Sediment delta from Thompson Creek. Image: 3429-226-ST-ST1 - 2/11/10



Wildlife Survey & Photo Service

2443 Fair Oaks Blvd. # 209 • Sacramento, CA 95825 • (916) 747-8537



Sediment delta from Thompson Creek. Image: 3429-226-ST-ST4 - 2/11/10



Sediment delta from Thompson Creek. Image: 3444-226A-ST-44 - 3/1/10

END