

9/1/2011
(Pre-construction)



9/26/2011



9/27/2011



10/1/2011



10/4/2011



10/13/2011



Wildlife Survey & Photo Service
2443 Fair Oaks Blvd. # 209 • Sacramento, CA 95825 • (916) 747-8537

Winters Putah Creek Park Sequential Images
All images © Ken W. Davis - from Winters Bike Bridge
9/1/2011 through 9/20/2018



10/25/2011
Creekbed wetted



10/28/2011
Pipes Removed



10/29/2011
Dam Removed



Wildlife Survey & Photo Service
2443 Fair Oaks Blvd. # 209 • Sacramento, CA 95825 • (916) 747-8537


Winters Putah Creek Park Sequential Images
All images © Ken W. Davis - from Winters Bike Bridge
9/1/2011 through 9/20/2018



11/1/2011
Water Clear



11/10/2011
Straw applied
to banks.



11/18/2011
Photo during storm / cloudy
skies



Wildlife Survey & Photo Service

2443 Fair Oaks Blvd. # 209 • Sacramento, CA 95825 • (916) 747-8537

Winters Putah Creek Park Sequential Images All images © Ken W. Davis - from Winters Bike Bridge **9/1/2011 through 9/20/2018**



12/28/11

Shows grass beginning to grow



1/23/12

Day after significant storm



3/14/12

Day after significant storm and
Spring Pulse flow



3/30/12



5/3/12



7-25-12
Irrigation pipes added.



Wildlife Survey & Photo Service

2443 Fair Oaks Blvd. # 209 • Sacramento, CA 95825 • (916) 747-8537

Winters Putah Creek Park Sequential Images All images © Ken W. Davis - from Winters Bike Bridge **9/1/2011 through 9/20/2018**



5 - 7 -13

Fish are actively using the creek within the Winters Parkway Project. Vegetation managed with planting, pruning, and irrigation.

To see subsurface video of fish in the Parkway Project go to:

www.creekman.com



6-23-14

Willows, alders and sedges planted by volunteers are healthy and getting larger. Note the sedges on the left bank and the willows on the right bank. Recently observed Tule Perch spawning in lower reach of the project. Other fish species are common in the entire project area.



5-31-2016

People using the creek. One of the project goals was to develop creek access for the public. Citizens commonly use this site for swimming, dog-walking and sunbathing.



Winters Putah Creek Park Sequential Images
All images © Ken W. Davis - from Winters Bike Bridge
9/1/2011 through 9/20/2018



1-11-2017
Flood conditions.
Note several avenues
of free-flowing flood
water.



2-7-2017
Flood conditions.



5-1-2017
After the significant
floods in the spring of
2017.



Wildlife Survey & Photo Service
2443 Fair Oaks Blvd. # 209 • Sacramento, CA 95825 • (916) 747-8537


Winters Putah Creek Park Sequential Images
All images © Ken W. Davis - from Winters Bike Bridge
9/1/2011 through 9/20/2018



7-24-2017



5-15-2018



9-20-2018

END